



















# INSTRUCCIONES DE ARMADO

Ax1 	Jx1 
Bx1 	Kx2  M8X40mm
Cx1 	Lx4  M8X25mm
Dx1 	Mx2  M8X20mm
Ex5 	Nx2  M8X25mm
Fx1 	Ox4  M6X20mm
Gx2(L/R) 	Px2  M5X12mm
Hx1 	Qx4 
Ix1 	Rx1 
	Sx1 M6 